


# PPDM Wellbore Symbols

Wellbore Status      Fluid Direction

Producing    Injecting    Suspended    Shut-In    Abandoned         
 Cycle Steam    Cycle Gas

Fluid Type

Fluid Type	Producing	Injecting	Suspended	Shut-In	Abandoned
Oil					
Oil Show					
Oil w/ Gas Show					
Gas					
Gas Show					
Gas w/ Oil Show					
Gas & Condensate					
Oil & Gas					
Oil & Gas Show					
Oil & Condensate					
Condensate					
Bitumen					
CO2					
Water					
Steam					
Sulphur					
WAG (Water Alt. Gas)					
WAS (Water Alt. Steam)					
Non-Combustable Gas					



### Improvement points:

1. Make status symbols all the same line weight and length.
2. Make type symbol borders the same line weight.
3. Make type symbol tick marks the same line weight and length.

This is a draft of vector-based PPDM wellbore status symbols. Some changes have been made without the consent of PPDM.

**DO NOT DISTRIBUTE. DRAFT ONLY.**